



Customer:
Icon Property Management

System:
Domestic Hot Water
Boiler

Problem



This boiler system was failing on a monthly basis. Home owners dealing with no hot water in the evening is a property manager's nightmare!

Solution

Local engineers put together specifications to install a high efficiency boiler and CPL was the company to install the new boilers.



How did we do?



"I had an exceptional experience dealing with CPL for a boiler retrofit at one of our high end Toronto condominiums. Their knowledge was impressive, and their execution was efficient and cost effective. I highly recommend CPL for your mechanical projects."

David Wallace VP of Field Operations – ICON Property Management

CALL US TODAY TO BOOK YOUR BUILDING'S
FREE SITE EVALUATION!

905-482-2962