



Customer:
Ivy North Corporation

System:
Underground sanitary sewer

Problem



This LCBO was under construction when the contractor noticed a piece of rebar had pierced through the plastic sanitary drains. The drains were buried under 12 feet of concrete and would have set the project back big time if an excavation were to take place.

Solution

CPL was contracted to remove the rebar, extract it, and install a structural liner to cover the hole and add integrity to the system. The project was created within budget and over just a few days.



How did we do?



“From our first meeting, we found Grayden and the team at CPL to be very professional and forthright regarding the solution they suggested. They completed the work on schedule and on budget, and provided a clean camera view of the repair after completion. As we all know in the construction game, delaying a project for any reason is costly to both the budget and reputation. As such, Ivy North would not hesitate to strongly recommend CPL to anyone in need of drain restoration, water safety, and general plumbing services.”

David Angelis Partner – Ivy North Corporation c/o LCBO

CALL US TODAY TO BOOK YOUR BUILDING'S
FREE SITE EVALUATION!

905-482-2962