



Customer:

MTCC #1348

System:

**Domestic Hot Water
System**

Problem



Pinhole Leaks! A common nuisance in high rise luxury. Pinhole leaks were draining this small buildings budget; they needed a solution before draining their bank account on endless service calls.

Solution

CPL provided the best solution at a cost effective price. That is to apply our coatings to the hot water system completely rejuvenating the flow and efficiency. This building saved 50% when they compared pipe lining vs repipe proving pipe lining to be the most viable solution.



How did we do?



"I found this firm, CPL, to be knowledgeable in their industry, professional, clean and their work was completed in a timely manner and within budget! They worked hand in hand with our superintendent and left each unit as they found it, clean!"

***Teresa Caprarella , Senior Property Manager General Property
Management MTCC #1348***

CALL US TODAY TO BOOK YOUR BUILDING'S
FREE SITE EVALUATION!

905-482-2962