




Customer:

MTCC #544

System:

**Domestic Hot Water
System**

Problem



The hot water risers were experiencing pinhole leaks and burst pipes.

Solution

R&G was contracted to replace all the hot water piping in the building. Perfect scheduling and water on by 5pm every day marked another successful project in the books for R&G.



How did we do?



“We had a flawless project and to date have had no complaints. The crew was very polite and accommodating to all of the residents.”

Angela LaGrotta Property Manager MTCC #544

CALL US TODAY TO BOOK YOUR BUILDING'S
FREE SITE EVALUATION!

905-482-2962