



Customer:
Ontario Power Generation

System:
8" Vertical Sanitary Stack

Problem



This project was a pipe replacement going on by a local plumbing contractor. When the plumbers noticed that a few stacks were completely inaccessible, pipe lining was the only option!

Solution

CPL restored the vertical sanitary pipe 20 floors while core drilling through connection points to ensure the entire pipe was restored. There was no need to remove drywall or even interrupt the daily operations, all the work was done at night.



How did we do?



“This 18 floor building was presenting a challenging drain problem. CPL Technologies was able to provide successful cleaning of the 8 “vertical Sanitary Stacks to maintain the pipe's structural integrity, which required patience to avoid any possible damage to the property. CPL Technologies showed care to the property, and maintained an urgent willingness to address all of the customers concerns.”

Manny Filantris Firenza Plumbing c/o (OPG) 700 University

CALL US TODAY TO BOOK YOUR BUILDING'S
FREE SITE EVALUATION!

905-482-2962