



Customer:  
PCC #423

System:  
Domestic Hot Water  
System

## Problem



An ageing building was adamant on pipe replacement for their corroding hot water risers.

## Solution

CPL was contracted to completely retrofit the hot water risers with new type "L" copper pipe. The project was successfully completed within a timely manner while cleanliness and professionalism stood out every day amongst the crew.



## How did we do?



"I had an excellent experience dealing with CPL Mechanical. Their level of professionalism and organization was greatly appreciated during such a complicated project, such as the full building pipe replacement."

Tatiana Vostrikov Property Manager – PCC #423

CALL US TODAY TO BOOK YOUR BUILDING'S  
FREE SITE EVALUATION!

905-482-2962