



**Customer:**  
YCC #76

**System:**  
Main sanitary sewer system  
servicing 3 building  
(Over 1000 units)

## Problem



The 12" sanitary sewer running under the parking garage and into the streets was falling apart. We could see the collapsed pipe through a pit in the garage. Some storm drains in the same garage were also victim of collapsed joints, when it rains it pours!!

## Solution

CPL installed a structural liner throughout the drainage system to restore the cast iron pipes and renew the structural integrity of the system. During the process CPL had to create a bypass to control the steady stream of water. This proved to be a highly technical job which was completed with perfection by the CPL crew.



## How did we do?



"Canada Pipe Lining Technologies Ltd did the best possible job for my property and used only the best job practices in providing the highest level of performance and an outstanding finished product. CPL has proven that they are extremely knowledgeable with regards to this particular technology."

**Vatchik Balasan – Property Manager YCC #76**

CALL US TODAY TO BOOK YOUR BUILDING'S  
FREE SITE EVALUATION!

**905-482-2962**