



Customer:
Chrysler Plant

System:
Large 6" drains for holding tanks

Problem



These large holding tanks were fitted with 6" and 8" drain pipes that were popping holes due to the chemicals in the water and causing flooding into the factory. The pipes were buried under concrete with 2000 gallon holding tanks sitting directly above, ouch!

Solution

CPL was called in on a weekend to fix the problem, crews jumped at the opportunity to mobilize to the Chrysler plant and start the process of lining the failing pipes. CPL technicians worked together with the factory workers to ensure the job was flawless. The pipes were restored and in working condition by Monday morning.



How did we do?



"I was impressed to know that CPL was willing to come out on the weekend and save our plant. Their crews were very professional and had a strong hold on the emergency repair, I highly recommend CPL for your emergencies."

Mike Gasso, Project Manager, Comstock Canada

CALL US TODAY TO BOOK YOUR BUILDING'S FREE SITE EVALUATION!
905-482-2962

R&G/CPL
 PLUMBING & PIPE LINING TECHNOLOGIES
 Where Efficient Solutions Meet Successful Results!

© Copyright 2015, All Rights Reserved. R&G/CPL Group