



Customer:
 Fairview Mall

System:
 Underground Sanitary
 Drains

Problem



This high end mall was experiencing major drainage problems just before the fall season, the drains were backing up on a daily basis and reactive snaking of the drains were not sufficient, a permanent solution was needed, and hopefully before the Christmas rush!

Solution

CPL carefully investigated this project and made a game plan to work in the evenings and early morning hours to ensure none of the stores or restaurants was disturbed. Hours of cleaning and CCTV inspections allowed us to install our structural liners through the mall drains which were buried under concrete and marble. CPL manages to restore all the problem drains adding a 50 year lifespan right on time for the Christmas rush.



How did we do?



“This wasn’t easy, some drains seemed to be at the point of no return but that’s what I love about this company, everyone is willing to get involved to ensure a successful project, even if it’s not their specialty. We never gave up and drove this project to success”

Grayden Hunt, Project Manager | Canada Pipe Lining Technologies Ltd



CALL US TODAY TO BOOK YOUR BUILDING'S
 FREE SITE EVALUATION!
 905-482-2962



R&G/CPL
 PLUMBING & PIPE LINING TECHNOLOGIES
 Where Efficient Solutions Meet Successful Results!

© Copyright 2015, All Rights Reserved. R&G/CPL Group