



Customer:
Unilever Canada

System:
Sanitary System with
Constant Water Flow

Problem



A section of 10" pipe shifted due to large transport trucks driving back and forth on a daily basis. The shift in pipe was causing blockages and flooding on the factory roadway and excavation was not an option!

Solution

CPL was called upon to create a bypass for the continuous water stream in the 10" pipe, the bypass had to safely carry water to a different location while the CPL crews cleaned the pipe and installed their structural pipe liners to even out the shift and eliminate the problem sanitary pipe.



How did we do?



CALL US TODAY TO BOOK YOUR BUILDING'S
FREE SITE EVALUATION!

905-482-2962